

## **Turners Certified Imports 50 Point Check**

Report ID: 17,956,243

Version: 1

Created: 21 Mar 2019

## **Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Dashboard: Good

Subaru Make: **Body Style: Sedan** 

Odometer: 95,379 Kms Impreza Model:

7AT0GF09X19014029 2013 VIN: Year:

**Under Carriage & Under Bonnet Inspection Comments** 

Tidy.

**General Comments** 

Tidy AWD Impreza sedan.

Seats:	Good
Carpets:	Good
Panels:	Good

Timing Chain **Engine Timing Mechanism:** 


Not Applicable **Evidence of Cam Belt Replacement:** 


Replaced At (odometer reading):

**Road Conditions During Test Drive:** 


Dry

Electrical	
Battery	<b>/</b>
Head lights	
Tail lights	
Indicators	
Dashboard warning lights	
Wipers (front & rear)	
Window winder FL	
Window winder FR	
Window winder RL	
Window winder RR	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	
Reversing camera	•





Inspected by: Daryll Timms



Date: 21 Mar 2019