

Turners Certified Imports 50 Point Check

Report ID: 17,957,779

Version: 1

Created: 29 Mar 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Honda	Body Style:	Hatchback
Model:	FIT	Odometer:	95,657 Kms
Year:	2008	VIN:	7AT08G2YX19065676

<u>Under Carriage & Under Bonnet Inspection Comments</u>
Tidy.

General Comments

Good little hatch.

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

Engine Timing Mechanism:

Evidence of Cam Belt Replacement:

Not Applicable

Replaced At (odometer reading):

Road Conditions During Test Drive: Dry


Electrical	
Battery	
Head lights	
Tail lights	
Indicators	
Dashboard warning lights	
Wipers (front & rear)	
Window winder FL	
Window winder FR	
Window winder RL	
Window winder RR	

Rear view mirrors

Radio (basic test only)


CD (basic test only)

Reversing camera



Engine	
Oil level	
Smoke & fumes	
Performance	
Noise	
Cooling System	
Coolant condition	
Performance	
Radiator / Hoses (visual)	
Suspension	
Suspension performance	
Steering performance	
Shock absorbers	

Inspected by: Daryll Timms



Date: 29 Mar 2019

Signature: