

## **Turners Certified Imports 50 Point Check**

Report ID: 18,019,877

Version:

15 May 2019 Created:

## **Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Suzuki **Body Style: SUV** 

Odometer: 82,385 Kms Escudo Model:

2009 7AT0GK4MX19100472 VIN: Year:

**Under Carriage & Under Bonnet Inspection Comments** 

Tidy.

**Electrical** 

**General Comments** 

Clean, tidy 4WD Escudo.

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

Timing Chain **Engine Timing Mechanism:** 


Not Applicable **Evidence of Cam Belt Replacement:** 


Replaced At (odometer reading):


**Road Conditions During Test Drive:** 

Dry

Battery	
Head lights	
Tail lights	
Indicators	
Dashboard warning lights	
Wipers (front & rear)	
Window winder FL	
Window winder FR	
Window winder RL	
Window winder RR	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	







Tyres (lowest observed tread

Inspected by: Daryll Timms	Date:	15 May 2019
----------------------------	-------	-------------

Reversing camera

= Not applicable for this vehicle