

## Turners Certified Imports 50 Point Check

Report ID: 18,086,912

Version: 2

Created: 05 Oct 2018

Date: 05 Oct 2018

Signature: .....

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

CERTIFIED IMPORTED VEHICLES	diagnostic testing undertaken. accredited inspection agency an	The vehicle has undergone a thod been test driven up to 50km/h from	prough compliance check by an NZTA om cold.
Make: Mazda Model: MPV Year: 2007  Under Carriage & Under General Comments	Body Style: SUV Odometer: 99,816 Kms VIN: 7AT0C11EX18169 er Bonnet Inspection Comments	Seats: Good  Carpets: Good  Panels: Good  Dashboard: Good  Engine Timing Mechanism  Evidence of Cam Belt Rep  Replaced At (odometer re	placement: Not Applicable eading):
Electrical	Transmission & Drive	Engine	<b>Tyres</b> (lowest observed tread depth)
Battery	Operation	Oil level	Left front 7 mm
Head lights	Noise	Smoke & fumes	Right front 7 mm
Tail lights	Clutch	• Performance	Left rear 7 mm
Indicators	CV joints	Noise	Right rear 7 mm
Dashboard warning lights	s Wheel bearings	Cooling System	Spare N/A
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake	Madatory rioses (visual)	Heater fan
Window winder RR		Suspension	Seatbelts
Rear view mirrors	Keys & Locking	Suspension performance	
Radio (basic test only)	Central locking	Steering performance	
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key  ✓ = Pass X = Fail  ■ = Not applicable for this vehicle

Inspected by: Jason Law

Name: .....

Number of keys

Reversing camera