

Turners Certified Imports 50 Point Check

Report ID: 18,086,983

Date: 30 Oct 2018

Signature:

Version: 2

Created: 30 Oct 2018

Note: This report is not a warranty

CERTIFIED diagrammer d	nostic testing undertaken. The vehedited inspection agency and been t	nicle has undergone a thorough co est driven up to 50km/h from cold.	mpliance check by an NZTA
Model: Corolla	Body Style: Wagon Odometer: 119,210 Kms VIN: 7AT0H607X18144417 Innet Inspection Comments	Seats: Good Carpets: Good Panels: Good Dashboard: Good Engine Timing Mechanism: Evidence of Cam Belt Replacement: Replaced At (odometer reading): Road Conditions During Test Drive:	Timing Chain Not Applicable Wet
Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 5 mm
Head lights	Noise	Smoke & fumes	Right front 5 mm
Tail lights	Clutch	Performance	Left rear 4 mm
Indicators	CV joints	Noise	Right rear 4 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear) Window winder FL	Wheel balance	Coolant condition	Tools
	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL Window winder RR	Hand Brake	Suspension	Heater fan •
Rear view mirrors	Keys & Locking	Suspension performance	Seatbelts
Radio (basic test only)	Central locking	Steering performance	Horn
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key ✓ = Pass X = Fail • = Not applicable for this vehicle

1

Inspected by: Roger King

Number of keys

Reversing camera