

Turners Certified Imports 50 Point Check

Report ID: 18,091,706

Version: 2

Created: 05 Oct 2018

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

IMPORTED VEHICLES	agnostic testing undertaken. The veh ccredited inspection agency and been to	icle has undergone a thorough co est driven up to 50km/h from cold.	impliance check by an NZTA
Make: Subaru	Body Style: Wagon	Seats: Good	
Model: Exiga Year: 2010	Odometer: 110,946 Kms VIN: 7AT0GF1RX18009887	Carpets: Good	
Under Carriage & Under Bonnet Inspection Comments		Panels: Good	
		Dashboard: Good	
		Engine Timing Mechanism:	Cambelt
General Comments		Evidence of Cam Belt Replacement:	No
		Replaced At (odometer reading):	
		Road Conditions During Test Drive:	Dry
Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 7 mm
Head lights	Noise	Smoke & fumes	Right front 7 mm
Tail lights	Clutch	Performance	Left rear 7 mm
Indicators	CV joints	Noise	Right rear 7 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR			160 ii
Window winder RL	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RR	Hand Brake	Suspension	Heater fan
Rear view mirrors	Keys & Locking	Suspension performance	Seatbelts
Radio (basic test only)	Central locking	Steering performance	Horn
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key ✓ = Pass X = Fail
Reversing camera	Number of keys 2		Not applicable for this vehicle

Inspected by: Jason Law

Date: 05 Oct 2018