

## Turners Certified Imports 50 Point Check

Report ID: 18,096,576

Version:

Created: 05 Oct 2018

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

CERTIFIED IMPORTED VEHICLES	inostic testing undertaken. The vereited inspection agency and been	test driven up to 50km/h from cold.	mpliance check by an NZTA
Make: Mazda Body Style: SUV  Model: MPV Odometer: 110,487 Kms  Year: 2007 VIN: 7AT0C11EX18158961  Under Carriage & Under Bonnet Inspection Comments  General Comments		Seats: Good  Carpets: Good  Panels: Good  Dashboard: Good  Engine Timing Mechanism:  Evidence of Cam Belt Replacement:  Replaced At (odometer reading):	Timing Chain Not Applicable
Electrical	Transmission & Drive	Road Conditions During Test Drive:  Engine	Dry  Tyres (lowest observed tread
Battery		Oil level	depth)  Left front 4 mm
Head lights	Noise	Smoke & fumes	Right front 4 mm
Tail lights	Clutch	Performance	Left rear 4 mm
Indicators	CV joints	Noise	Right rear 4 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare N/A
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL  Window winder RR	Hand Brake	Suspension	Heater fan
Rear view mirrors	Keys & Locking	Suspension performance	Seatbelts
Radio (basic test only)	Central locking	Steering performance	Horn
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key  ✓ = Pass X = Fail

•

Reversing camera

Inspected by: Jason Law

1

Number of keys

= Not applicable for this vehicle

Date: 05 Oct 2018