

Report ID: 18,101,303 Version: 1 25 Jun 2018 Created:

Make: Hyundai Model: Accent Body Style: Ha	itchback Pass Fail N	/A
	Aug 2018 Engine	
	101303 Oil level ✓	—
VIN: KMHCT51DMFU2090C Next Service: 45000 Service History:	No Smoke & fumes	
	Performance	
Note: This report is not a warranty	Neize	
This report is a guide only. Consideration is made for age and mileage. Parts have not be diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Ven	en dismantied or	
a full mechanical inspection prior to purchase and this can be arranged for an additional char		
	Performance	
Key:	Radiator / Hoses (visual)	
S = scratch	Transmission	
D=dent SC	Operation V	
	Noise V	
PT = paint defect C = crack	SC Clutch	_
P = pin dent	CV joints	
* = decals PSC PIP		
SC = stone chips	Wheel bearings	
W = significant scuffs		
Body Inspection Comments	J	
	Tyres (lowest observed tread depth of tyres)	
	Left front 7 mn	
	Right front 7 mn	
	Left rear 6 mn	
Conditions During Body Inspection: Dry	Right rear 6 mn	n
Under Carriage & Under Bonnet Inspection Comments	Spare Yes	
onder carnage & onder bonnet inspection comments	Suspension	
	Suspension performance 🗸	
	Steering performance 🖌	
	Shock absorbers 🖌	
	Air Conditioning / Heater	
Interior Comments	Operation 🖌	
Good	Electrical / Accessories	
Seats	Head lights 🖌	
Carpets Good	Tail lights	
	Indicators 🖌	
Panels	Dashboard warning lights 🖌	
Dashboard	Wipers (front & rear)	
	Window winder FL 🖌	
	Window winder FR 🖌	
<u>General Comments</u>	Window winder RL 🖌	
	Window winder RR 🖌	
	Rear view mirrors	
	Radio (basic test only)	
	CD (basic test only)	
	Number of keys 2	
Road Conditions During Test Drive: Wet	Central locking 🖌	
	Remote locking	
Engine Timing Mechanism: Timing Chain	Sat. Nav. (basic test only)	/
Evidence of Cam Belt Replacement: Not Applicable Kms:	Reversing camera 🖌	
		_
Inspected by: John Lindsay	Date: 25 Jun 2018	

I have read and understood this condition guide.

Name:

Signature: