

## Turners Certified Imports 50 Point Check

Report ID: 18,260,320

Version: 3

Created: 16 Oct 2018

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA

IMPORTED VEHICLES	accredite	ed inspection agency a	nd been tes	st driven up to	50km/h fron	n cold.		Í		
Make: Toyota Body Style: Wagon Model: Corolla Odometer: 93,347 Kms Year: 2009 VIN: 7AT0H607X18090536  Under Carriage & Under Bonnet Inspection Comments  General Comments				Seats: Good  Carpets: Good  Panels: Good  Dashboard: Good  Engine Timing Mechanism: Timing Chain  Evidence of Cam Belt Replacement: Not Applicable  Replaced At (odometer reading):						
				Road Condit	tions During Te	st Drive:	Dry			
Electrical Transmission & Drive							<b>Tyres</b> (lowest obs depth)	<b>es</b> (lowest observed tread th)		
Battery		Operation		Oil level			Left front	5	mm	
Head lights		Noise		Smoke & fur	mes		Right front	5	mm	
Tail lights		Clutch	•	Performance	e [		Left rear	5	mm	
Indicators		CV joints		Noise			Right rear	5	mm	
Dashboard warning lights		Wheel bearings		Cooling Sys	stem		Spare	Yes		
Wipers (front & rear)		Wheel balance		Coolant con	dition	/	Tools			
Window winder FL		Brakes		Performance	L		Interior			
Window winder FR		Performance		Radiator / Ho	L		AC Operation	Ī		
Window winder RL		Hand Brake			,,	•	Heater fan			
Window winder RR			•	Suspension			Seatbelts			
Rear view mirrors		Keys & Locking		Suspension	performance		Horn	[		

•

Central locking

Remote locking

Number of keys

Radio (basic test only)

CD (basic test only)

Reversing camera

1

Steering performance

Inspected by: Dion Mair

**Shock absorbers** 

Date: 16 Oct 2018

**X** = Fail = Not applicable for this vehicle

**Turners Certified Key** 

✓ = Pass