

Report ID: 18,271,779 Version: 2 Created: 15 Aug 2018

| Make: | Suzuki | Model: | Swift | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|--|-----------------|------------------------|---------------------------------|----------------------|--|------|------|-----|
| Year: | Registration: LMP234 Reg Expiry: 17 Jul 2019 | | | | Engine | | | | |
| WoF Expiry: | , | Odometer: | 75,230 Kms | Good No: | 18271779 | Oil level | ~ | | |
| VIN: | JSAFZC32S00300991 | Next Service: | | Service Histor | y: Yes | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | eration is made | for age and mileage | Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and th | his can be arranged fo | r an additional c | harge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch D = dent | | | | | | Transmission | | | |
| R = rust | sc | | | 210 | SPTC | Operation | ~ | | |
| PT = paint defe | | r I | | $\left[\left(\right) \right]$ | | Noise | ~ | | |
| C = crack | | | | | SC | Clutch | ~ | | |
| P = pin dent | | | | | | CV joints | ~ | | |
| * = decals SC 919 | | | | | | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs W | | | | | | Performance | ~ | | |
| Body Insr | ection Comments | Note: som | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Body Inspection Comments Rear bumper misaligned | | | | | | Tyres (lowest observed tread depth of tyres) | | | es) |
| Audio antenna missing | | | | | | Left front | 4 mm | | mm |
| Stone chips on front windscreen CVA Rear bumper cracked and paint defect | | | | | | Right front | 2 | 1 | mm |
| | | | | | | Left rear | 5 | 5 | mm |
| Conditions During Body Inspection: Wet | | | | | | Right rear | 5 mm | | mm |
| wet | | | | | | Spare | N/A | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation 🖌 | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | ra | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General Comments | | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | < | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | | |
| Road Con | ditions During Test | Central locking | ~ | | | | | | |
| | | | | | | Remote locking | ~ | | |
| Engine Tir | Sat. Nav. (basic test only) | | | ~ | | | | | |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | | | ~ |
| | | | | | | | 10 | | |
| Inspected by: Xinghui Lin Date: 15 Aug 2018 | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: