

Turners Certified Imports 50 Point Check

Report ID: 18,279,071

Version: 3

Created: 31 Oct 2018

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:			Hatchback
Model:			43,930 Kms
Year:	2009	VIN:	TSMEXB32S00215717
Under (Carriage & Under Bor	nnet Inspec	tion Comments

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

General Comments		

Engine Timing Mechanism:


Evidence of Cam Belt Replacement:


Replaced At (odometer reading):

Road Conditions During Test Drive:


Dry







Inspected by: Sean Butcher



Tyres (lowest observed tread

Date: 31 Oct 2018