

## **Basic Vehicle Condition Guide**

Report ID: 18,283,670

Version: 1

Engine

Oil level

Smoke & fumes

Created: 30 Jul 2018

Pass

~

N/A

Fail

Make: Subaru Model: Impreza Body Style: Hatchback


 Year:
 2,009
 Registration:
 Reg Expiry:

 WoF Expiry:
 13 Jul 2019
 Odometer:
 70,665 Kms
 Good No:
 18283670

 VIN:
 7AT0GF09X18026154
 Next Service:
 80,000kms
 Service History:
 No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Dry

Under Carriage & Under Bonnet Inspection Comments

Conditions During Body Inspection:

Tidy.

Interior Comment	<u>'S</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

## **General Comments**

Nice 2WD hatch.

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

**Daryll Timms** 

Evidence of Cam Belt Replacement: No

Kms:

Performance ~ Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation Noise 1 Clutch 1 CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm Right front mm 2 Left rear 5 mm Right rear  $\mathsf{mm}$ 5 Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 1 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera

I have read and understood this condition guide.

Name:			

30 Jul 2018

Date: