

Turners Certified Imports 50 Point Check

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Honda	Body Style:	SUV
Model:	Stream	Odometer:	130,159 Kms
Year:	2010	VIN:	7AT08GADX18131985

Under Carriage & Under Bonnet Inspection Comments

Seats:	Good		
Carpets:	Good		
Panels:	Good		
Dashboard:	Good		
Engine Timi	ng Mechanism:	Timing Chain	

Evidence of Cam Belt Replacement:

Not Applicable

Dry

Replaced At (odometer reading):

Road Conditions During Test Drive:

General	Comments

			Road Conditions During Test Drive: 219				
Electrical	Transmission &	Drive	Engine		Tyres (lowest observed tread depth)		
attery	Operation		Oil level		Left front	7	m
ead lights	Noise		Smoke & fumes		Right front	7	m
il lights	Clutch	•	Performance		Left rear	7	m
dicators	CV joints		Noise		Right rear	7] m
ashboard warning light	Wheel bearings		Cooling System		Spare	Yes	
ipers (front & rear)	Wheel balance		Coolant condition		Tools	V	
indow winder FL	Brakes		Performance		Interior		
ndow winder FR	Performance		Radiator / Hoses (visual)		AC Operation	Ĩ	
ndow winder RL	Hand Brake		,		Heater fan		V
ndow winder RR			Suspension		Seatbelts		V
ar view mirrors	Keys & Locking		Suspension performance		Horn		· V
adio (basic test only)	Central locking		Steering performance				~
D (basic test only)	Remote locking		Shock absorbersTurners Certified Key \checkmark = PassX = Fail \bullet = Not applicable for this vertice				
eversing camera	Number of keys	2	Inspected by: John Linds	say		23 Oct 2018	

Signature: