

Turners Certified Imports 50 Point Check

Report ID: 18,310,360

Version:

Created: 16 Oct 2018

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

IMPORTED VEHICLES	decreated mape	ection agency and been	rest diverrup to				
Make: Mazda	Body Style:	Sedan	Seats:	Good			
Model: Atenza Year: 2013		77,473 Kms 7AT0C139X18103474	Carpets:	Good			
Under Carriage & Und	ler Bonnet Inspect	ion Comments	Panels:	Good			
			Dashboard:	Good			
			Engine Timi	ng Mechanism:	Timing Chain		
General Comments		Evidence of	Cam Belt Replacem	ent: Not Applicable	Not Applicable		
				(odometer reading	M		
			Road Condi	tions During Test Dr			
Electrical	Trans	mission & Drive	Engine		Tyres (lowest observed)	erved tread	
Battery	Opera	ation	Oil level		Left front	5 n	mm
Head lights	Noise		Smoke & fur	mes	Right front	5 n	mm
Tail lights	Clutch	•	Performance	e	Left rear	5 n	mm
Indicators	CV joi	nts	Noise		Right rear	5 n	mm
Dashboard warning ligh	ts Whee	I bearings	Cooling Sys	stem	Spare	N/A	
Wipers (front & rear)	Whee	I balance			Tools	X	
Window winder FL	Brake		Coolant con		Interior		
Window winder FR			,				_
Window winder RL	Perfor	rmance	Radiator / H	oses (visual)	AC Operation		<u></u>
Window winder RR	Hand	Brake	Suspension	1	Heater fan		
WITHGOW WITHGET THE					Coatholto		

•

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Reversing camera

Keys & Locking

Central locking

Remote locking

Number of keys

1

Suspension performance

Steering performance

Inspected by: Dion Mair

Shock absorbers

Date: 16 Oct 2018

X = Fail = Not applicable for this vehicle

Horn

Turners Certified Key

✓ = Pass