

Turners Certified Imports 50 Point Check

Report ID: 18,311,034

Version: 2

Created: 16 Oct 2018

Note: This report is not a warranty

Battery		Operation	Oil level		Left front 3 m	ım
Electrical		Transmission & Drive	Engine		Tyres (lowest observed tread depth)	
			Road Cond	itions During Test Drive	: Wet	
			Replaced A	t (odometer reading):		
General Comments			Evidence of	f Cam Belt Replacement	:: No	
			Engine Tim	ing Mechanism:	Cambelt	
			Dashboard	Good		
Under Carriage & Under Bonnet Inspection Comments			Panels:	Good		
Year: 2007	VIN:	7AT0GF09X18003111	Carpets:	Good		
Model: Impreza	Odor	neter: 95,041 Kms		Cood		
Make: Subaru	Body	Style: Hatchback	Seats:	Good		
Turners CERTIFIED IMPORTED VEHICLES	This reporting diagnostic accredited	rt is a guide only. Consideratic c testing undertaken. The ve d inspection agency and been	on is made for a hicle has unde test driven up t	age and mileage. Par ergone a thorough o o 50km/h from cold.	ts have not been dismantled c compliance check by an NZT	or A

Electrical	
Battery	
Head lights	
Tail lights	
Indicators	
Dashboard warning lights	
Wipers (front & rear)	
Window winder FL	
Window winder FR	
Window winder RL	
Window winder RR	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	
Reversing camera	•





