

Basic Vehicle Condition Guide

Report ID: 18,317,261

Pass

~

~

/

V

1

/

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Operation

Noise

Clutch

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR Window winder RL

Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 08 Aug 2018

Fail

N/A

1

mm

mm

mm

 mm

7

6

3

1

/

/

/

1

1


2

Yes

Make: Model: Mitsubishi L300 **Body Style:** Van Year: Registration: **Reg Expiry:** 10 Jul 2019 2,008 **ELN607 WoF Expiry: Odometer: Good No:** 19 Sep 2018 164,718 Kms 18317261 VIN: JMAHNP14V8A800326 **Next Service: Service History:** 170900 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Dirty

Interior Comments		
Seats	stains	
Carpets	Average	
Panels	Average	
Dashboard	Good	

C = = = = =	C
Generai	Comments

10 seats

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:**

	Remote locking	~		
	Sat. Nav. (basic test only)	~		
Kms:	Reversing camera	~		
Date: 08 Aug 2018				
Name: Signature:				

	110
Inspected by: Stuart Melbourne	
I have read and understood this conditio	n guid