

## **Basic Vehicle Condition Guide**

Report ID: 18,333,915


Version: 1

Created: 23 Aug 2018

Make: Model: Holden Captiva 7 **Body Style:** SUV Year: 2,014 Registration: HSB613 Reg Expiry: 23 Oct 2018 WoF Expiry: **Odometer:** 10 Oct 2018 **Good No:** 18333915 111,114 Kms VIN: KL3CD2669EB039921 **Next Service: Service History:** 121000

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

Rear bumper not fitting correctly LHS. Stonechips on windscreen. Cannot open cover over jack etc so cannot check if they are there. Wear on RF seat and mat.

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Average condition.

<u>Interior Comments</u>		
Seats	Average	
Carpets	Average	
Panels	Average	
Dashboard	Average	

## **General Comments**

Engine drive belt is noisy. Drives ok.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Roger King Date: 23 Aug 2018

Name: .....

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
~		
~		
<b>'</b>		
~		
l depth	of tyre	es)
	5	mm
		mm
		mm
1.		mm
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
<i>'</i>		
· ·		
· ·		
•		
•		
•		<u> </u>
2		
2		
2		
2 <b>v</b>		
2 • • • • • • • • • • • • • • • • • • •		<i>V</i>
	V V V V V V depth	V

Signature: .....