

Report ID: 18,335,462 Version: 1 Created: 24 Aug 2018

| Make: | Ford | Model: | Mondeo | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|--|----------------------|------------------------|--|-----------------------|------------------------------|------------|---------|-----|
| Year: | 2,013 | Registration: | GUE868 | Reg Expiry: | 07 Oct 2018 | Engine | | | |
| WoF Expiry: | 08 Apr 2019 | Odometer: | 99,715 Kms | Good No: | 18335462 | Oil level | ~ | | |
| VIN: | WF0EXXGBBECS80636 | Next Service: | 120000 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty a quide only Conside | eration is made | for age and mileage | Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and th | his can be arranged fo | or an additional o | charge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | | -01- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch D = dent | | | | | | Transmission | | | |
| D = dent R = rust | | | | 710 | HIV | Operation | ~ | | |
| PT = paint defe | | r I | | $\left(\left \left(\right) \right\rangle \right)$ | 7011 | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | HIP | | | | 74116 | CV joints | ~ | | |
| * = decals | sc 916 | | | To . | ED w | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| vv = significant | | | | | | Performance | ~ | | |
| Body Incr | pection Comments | Note: som | ne defects & blemishes | s may not be disp | played in the diagram | Hand Brake | ~ | | |
| | bection comments | | | | | Tyres (lowest observed tread | l depth | of tyre | es) |
| | | | | | Left front 3 m | | | | |
| | | | | | | Right front | | 3 | mm |
| | | | | | | Left rear | | 1 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | | 5 | mm |
| Conditions During Body Inspection: Dry | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | 1 |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | . Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd | | | | | Window winder FL | ~ | | |
| | 1 | | | | | Window winder FR | ~ | | |
| <u>General C</u> | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | | 1 |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | ~ | | |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | ~ | | |
| | | | | | | | | 1 | |
| Inspected by: Brad Lucas Date: 24 Aug 2018 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: