

Turners Certified Imports 50 Point Check


Report ID: 18,339,076


Version: 3

Created: 26 Sep 2018

Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold. Make: Mitsubishi **Body Style: SUV** Average Seats: RVR Odometer: 818,119 Kms Model: Average Carpets: 2010 7AT0CJ1KX18012495 VIN: Year: Good Panels: **Under Carriage & Under Bonnet Inspection Comments** Dashboard: Good Timing Chain **Engine Timing Mechanism: General Comments** Not Applicable **Evidence of Cam Belt Replacement:** Replaced At (odometer reading): Dry **Road Conditions During Test Drive: Tyres** (lowest observed tread **Electrical Transmission & Drive Engine** depth) 7.2 mm **Battery** Operation Oil level Left front 7.4 mm **Head lights** Noise Smoke & fumes Right front 4.7







Inspected by: lan Dunn

Date: 26 Sep 2018

mm