

Report ID: 18,489,948 Version: 1 Created: 30 Aug 2018

| Make: | Toyota | Model: | Hilux | Body Style: | Utility | | Pass | Fail | N/A |
|--|--------------------------|-----------------|------------------------|--------------------|------------------|--|------|-------|-------------|
| Year: | 2,004 | Registration: | CDP900 | Reg Expiry: | 29 Jul 2019 | Engine | I | I | 1 |
| WoF Expiry: | 09 Mar 2019 | Odometer: | 357,661 Kms | Good No: | 18489948 | Oil level | ~ | | |
| VIN: | JTFDV696600023819 | Next Service: | 364,000 | Service Histor | y: No | Smoke & fumes | ~ | | + |
| | | | | | | Performance | ~ | | |
| Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or | | | | | | Noise | ~ | | + |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechar | ical inspection prior to | purchase and tl | his can be arranged fo | or an additional c | harge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | S*SC W | -0 | * SC SC | | D PT SC W | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | L |
| D = dent | s di | | | The | | Operation | ~ | | |
| R = rust | | | | í l n | JHIH | Noise | ~ | | |
| PT = paint defect C = crack | | | | | | Clutch | ~ | | |
| P = pin dent | HIC | | | | | CV joints | ~ | | |
| * = decals S SC W PIP | | | | | | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | V | | |
| W = significant scuffs * SC W W P SC SC W W D SC W | | | | | | Performance | ~ | | |
| | | Nataron | | | | Hand Brake | ~ | | |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram | | | | | | | | oftur |)) |
| Paint worn on inner sills/ rear wheel arches in poor condition Paint worn on tailgate with surface rust | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| L/H rear tail light lens cracked | | | | | | | | 4 | mm |
| Keys won't | operate door locks | | | | | Right front | | 5 | mm |
| | | | | | | Left rear | | 9 | mm |
| Conditions During Body Inspection: Wet | | | | | | Right rear | 9 mm | | mm |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare Yes | | | |
| | inage & onder bor | meenspeede | <u>on comments</u> | | | Suspension | | 1 | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| Interior Comments | | | | | | Operation | | ~ | |
| | Average | | | | | Electrical / Accessories | 1 | 1 | |
| Seats | /weitige | | | | | Head lights | ~ | | - |
| Carpets | Marks / sta | ains | | | | Tail lights | ~ | | |
| | Average | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| Dashboa | rd Screw hole | es | | | | Wipers (front & rear) | ~ | | ļ! |
| | | | | | | Window winder FL | ~ | | <u> </u> |
| | ~ . | | | | | Window winder FR | ~ | | |
| General Comments | | | | | Window winder RL | ~ | | | |
| Exhaust rattles No belt on air con pump / air con pump not working | | | | | | Window winder RR | ~ | | |
| Oil leak in r | ear differential | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | | ~ | |
| | | | | | | Number of keys | 2 | | |
| Road Conditions During Test Drive: Wet | | | | | | Central locking | | ~ | |
| | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Cambelt | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | 10 | Kms: | | Reversing camera | | | ~ |
| | | | | | | | | | |
| Inspected by: Murray Craig Date: 30 Aug 2018 | | | | | | | | | |
| I have read and understood this condition guide. Name: | | | | | | | | | |