

7AT0GF09X18004803

Basic Vehicle Condition Guide

Report ID: 18,499,238

Version: 2

Created: 09 Nov 2018

Fail

Pass

×

X X

X

X

X

X

X

X

X

X

3.0

2.0

7.0

7.0

X

X

X

X

X

X

X

x

X

X

X

X

X

X

X

×

1

X

X

07 Sep 2018

X

X

Yes

mm

mm

mm

 mm

Tyres (lowest observed tread depth of tyres)

N/A

Make: Subaru Model: Impreza **Body Style:** Hatchback

Year: 2007 Registration:

18499238

Reg Expiry:

Service History:

Engine

Noise

Cooling System

Performance

Transmission Operation

Noise

Clutch

Brakes Performance

CV joints

Wheel bearings

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Suspension performance

Steering performance

Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL

Window winder FR

Window winder RL

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Date:

Shock absorbers

Operation

Head lights

Tail lights

Indicators

Spare

Coolant condition

Radiator / Hoses (visual)

WoF Expiry: 31 Aug 2019

VIN:

Odometer: Next Service:

96,446 Kms **Good No:** Oil level X Smoke & fumes X Performance X

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

106,000kms

Key:	
S = scratch	
D = dent	
R = rust	
PT = paint defect	
C = crack	
P = pin dent	
* = decals	
SC = stone chips	
W = significant scut	fs
Body Inspect	ion Comments Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tidy.

Interior Comments		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

General Comments

Good AWD STi hatch.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement:

I have read and understood this condition guide.

Yes

Kms:

91,000

Inspected by:	Daryll Timms

Name:	Signature: