

Report ID: 18,504,771 Version: 1 Created: 12 Sep 2018

Make:	Holden	Model:	Astra	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,006	Registration:	DHL158	Reg Expiry:	15 Jul 2019	Engine		1	1
WoF Expiry:	22 Sep 2019	Odometer:	166,262 Kms	Good No:	18504771	Oil level	~		
VIN:	W0L0AHL4855191987	Next Service:	165,000 kms	Service Histor	V: No	Smoke & fumes	~		
						Performance	v		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	· ·		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:	sc	-0	SC		sc	Radiator / Hoses (visual)	• •		
S = scratch						Transmission			
D = dent S SCW						Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack	ect			+	S D R SC	Clutch	V		
C = Crack P = pin dent	Ho								~
* = decals	DRSC DR				ANA	CV joints	~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs S W						Brakes			1
		Notocom	a defecte & blomister		laved in the diagram	Performance	V		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	/	-6-	
Casing on left wing mirror is cracked. Hightop taillight is cracked. Rubber mouldings on roof are						Tyres (lowest observed tread depth of tyres			
worn/cracked.						Left front	4.2		mm
						Right front	4	.0	mm
						Left rear		.5	mm
Conditions During Body Inspection: Dry						Right rear	3	3.4 m	
Linder Carriege & Linder Depart Inspection Comments						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Water low i	n overflow, wet around	thermostat?				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			-
						Operation	~		
Interior Comments Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpots	Good					Tail lights		~	
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Deal-	Good					Wipers (front & rear)	~		
Dashboa	iiu					Window winder FL	~		
	_					Window winder FR	~		
General Comments						Window winder RL	~		
One key has broken but can still be used. Small tear in right rear seat.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
			ыу			Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	′es	Kms: 12	1,047	Reversing camera			~
									1
Inspected by: Anna-Lise Ferguson Date: 12 Sep 2018									
I have read	and understood th	is condition c	uide. Name: .			Signature:			