

Basic Vehicle Condition Guide

Report ID: 18,558,949


Version:

Created: 12 Sep 2018

Make: Model: Suzuki Swift **Body Style:** Hatchback Year: 2,014 Registration: Reg Expiry: **HMJ606** 10 Dec 2018 **Odometer:** WoF Expiry: 20 Sep 2018 **Good No:** 18558949 60,471 Kms VIN: **Next Service: Service History:** JSAFZC82S00305601 72000

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Left hand taillight cracked Rear bumper not fitted correctly Windscreen chips

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Bonnet bracket bent right hand side Bonnet stay and clip missing Right front guard damaged Damage left sill

Interior Comments	
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: **Timing Chain**

Evidence of Cam Belt Replacement: Kms: Not Applicable

12 Sep 2018 Inspected by: John Lindsay Date:

Name:

h of tyre 4	wes) mm mm mm
4	mm
-	
5	mm
5	
Yes	
~	
1	-
	~
	~
	Yes

Signature: