

Report ID: 18,570,276 Version: 2 Created: 30 Oct 2018

| Make: | Holden | Model: | Commodore | Body Style: | Wagon | | Pass | Fail | N/A |
|--|--------------------|----------------------|----------------|----------------|-------------|------------------------------|------|------------------|------------|
| Year: | 2012 | Registration: | GQG592 | Reg Expiry: | 21 Nov 2018 | Engine | | | |
| WoF Expiry: | 08 Feb 2019 | Odometer: | 209,274 Kms | Good No: | 18570276 | Oil level | | ~ | |
| VIN: | 6G1EK8E56CL660285 | Next Service: | 215,400kms | Service Histor | V: No | Smoke & fumes | V | | |
| | | | | | | Performance | ~ | | |
| Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or | | | | | | Noise | ~ | | |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| | | | | | | Coolant condition | | ~ | |
| | | | C.W. | | W | Performance | ~ | | |
| Key: | SC S | -0 | SW W | | | Radiator / Hoses (visual) | V | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent R = rust PT = paint defect | | | | | | Operation | ~ | | |
| | | | | | | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | | | | | | CV joints | | | ~ |
| * = decals SDSC 000 W | | | | | | Wheel bearings | ~ | | - |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs SC W S S W S P W | | | | | | Performance | | ~ | |
| | | | | | | Hand Brake | ~ | • | |
| Body Inspection Comments | | | | | | Tyres (lowest observed tread | • | oftvre | <u>د (</u> |
| Plastic panel on right side of base of drivers seat is cracked & broken. Hole in drivers seat back rest. Left side carpet panel in boot area has a large part of it cut out. Stone chips in windscreen. Hole in roof, 2 x R/T aerial bases fitted to roof. | | | | | | Left front | | | |
| | | | | | | Right front | | 5.4 mm 5.6 mm | |
| | | | | | | Left rear | | | mm |
| | | | _ | | | Right rear | | .6 | mm |
| Conditions During Body Inspection: Dry | | | | | | | 7.2 | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare Yes Suspension | | | |
| <u></u> | | | | | · · | | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| Interior Comments | | | | | | Operation | ~ | | |
| Good | | | | | | Electrical / Accessories | | | |
| Seats | | | | | | Head lights | ~ | | |
| Carpets | Good | | | | | Tail lights | ~ | | |
| | Average | | | | | Indicators | ~ | | |
| Panels | Avelage | | | | | Dashboard warning lights | ~ | | |
| Dashboa | Good Good | | | | | Wipers (front & rear) | ~ | | |
| | - | | | | | Window winder FL | ~ | | |
| Concret | Commonte | | | | | Window winder FR | ~ | | |
| <u>General Comments</u> EX NZ police car. Metal plate fitted on top of dashboard & over pocket under heater controls. Panels on right | | | | | | Window winder RL | ~ | | |
| EX NZ police car. Metal plate fitted on top of dashboard & over pocket under neater controls. Panels on right side of centre console not fitting correctly. Bolt holes in left front floor, by centre console. Cup holder base is missing. Front radio speakers not working. | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 5 2 | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| lana antal langu Vauna | | | | | | | | | |
| Inspected by: Jason Young Date: 04 Oct 2018 | | | | | | | | | |
| I have read and understood this condition guide. Name: | | | | | | | | | |