

Turners Certified Imports 50 Point Check

Report ID: 18,574,097 Version: 2 Created: 12 Jun 2019

Note:	This I	report	is not	t a	warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Subaru	Body Style:	SUV
Model:	Forester	Odometer:	91,718 Kms
Year:	2008	VIN:	7AT0GF17X18007228

Under Carriage & Under Bonnet Inspection Comments

Seats:	Good		
Carpets:	Good		
Panels:	Average		
Dashboard:	Good		
Engine Timir	ng Mechanism:	Cambelt	

Dashboard: Good	
Engine Timing Mechanism:	Cambelt
Evidence of Cam Belt Replacement:	No
Replaced At (odometer reading):	

Road Conditions During Test Drive:	Dry
------------------------------------	-----

General Comments

ilectrical		Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery		Operation 🔰	Oil level	Left front 7.0 mm
lead lights		Noise	Smoke & fumes	Right front 7.0 mm
il lights		Clutch	Performance	Left rear 7.0 mn
dicators		CV joints	Noise	Right rear 7.0 mn
ashboard warning lights		Wheel bearings	Cooling System	Spare Yes
ipers (front & rear)		Wheel balance	Coolant condition	Tools
indow winder FL		Brakes	Performance	Interior
indow winder FR		Performance	Radiator / Hoses (visual)	AC Operation
ndow winder RL		Hand Brake		Heater fan
ndow winder RR			Suspension	Seatbelts
ar view mirrors		Keys & Locking	Suspension performance	Horn
dio (basic test only)		Central locking	Steering performance	
D (basic test only)		Remote locking	Shock absorbers	Turners Certified Key✓= Pass✓= Fail•= Not applicable for this vehicle
eversing camera	•	Number of keys 1	Inspected by: John Lindsay	Date: 11 Dec 2018

Signature: