

Turners Certified Imports 50 Point Check

Report ID: 18,577,158

Version:

Created: 01 Oct 2018

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Mazda **Body Style: Hatchback** Axela Odometer: 94,355 Kms Model:

2013 7AT0C13JX18209417 VIN: Year:

Under Carriage & Under Bonnet Inspection Comments

Tidy.

General Comments

Good Axela hatch.

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

Timing Chain **Engine Timing Mechanism:** Not Applicable

Replaced At (odometer reading):

Evidence of Cam Belt Replacement:

Dry **Road Conditions During Test Drive:**


Electrical Battery Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors


Radio (basic test only)

CD (basic test only)

Reversing camera

ransmission & D	rive
Operation	
Noise	
Clutch	•
CV joints	
Wheel bearings	
Wheel balance	
Brakes	
Performance	
Hand Brake	
Keys & Locking	
Central locking	
Remote locking	
Number of keys	2





Inspected by: Daryll Timms Date: 01 Oct 2018
--