

Turners Certified Imports 50 Point Check

Report ID: 18,583,879

Version:

Created: 08 Oct 2018

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

IMPORTED VEHICLES	accredite	d inspection agency and	he vehicle has und I been test driven up	to 50km/h from	ugh con cold.	npliance check	by an N	ZIA	
Make: Volkswagen Body Style: Hatchback Model: Golf Odometer: 48,434 Kms Year: 2009 VIN: WVWZZZ1KZAW033919 Under Carriage & Under Bonnet Inspection Comments General Comments			Panels: Dashboard Engine Tin Evidence of Replaced A	Carpets: Good					
Electrical		Transmission & Drive	Engine			Tyres (lowest obse depth)	rved tread		
Battery		Operation	Oil level	6		Left front	6	mm	
Head lights		Noise	Smoke & f	rumes 🕒		Right front	6	mm	
Tail lights		Clutch	Performan	nce		Left rear	5	mm	
Indicators		CV joints	Noise	6		Right rear	5	mm	
Dashboard warning light	s	Wheel bearings	Cooling S	vstem		Spare	Yes		
Wipers (front & rear)		Wheel balance	Coolant co			Tools			
Window winder FL		Brakes	Performan	_		Interior			
Window winder FR		Performance	Radiator /	Hoses (visual)		AC Operation			
Window winder RL		Hand Brake			_	Heater fan			
Window winder RR			Suspension	on		Seatbelts			
Rear view mirrors		Keys & Locking	Suspensio	on performance		Horn			
Radio (basic test only)		Central locking	Steering p	performance		T			
· ·					-	TILLUM ONE CONSIST A I			

•

Remote locking

Number of keys

CD (basic test only)

Reversing camera

1

Shock absorbers

Inspected by: Hamish McDonald

Date: 08 Oct 2018

X = Fail = Not applicable for this vehicle

✓ = Pass