

Turners Certified Imports 50 Point Check

Report ID: 18,590,475

Version: 1

Created: 08 Oct 2018

Date: 08 Oct 2018

Signature:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold

CERTIFIED IMPORTED VEHICLES	accredited inspection agency and	he vehicle has undergone a thorough c I been test driven up to 50km/h from cold.	ompliance check by an NZTA
Make: Toyota	Body Style: Van	Seats: Good	
Model: Hiace Year: 2014	Odometer: 107,576 Kms VIN: 7AT0H60FX18143	929 Carpets: Good	
Under Carriage & Under Bonnet Inspection Comments		Panels: Good	
		Dashboard: Good	
		Engine Timing Mechanism:	Cambelt
General Comments		Evidence of Cam Belt Replacement	: No
		Replaced At (odometer reading):	
		Road Conditions During Test Drive	: Dry
Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 7 mm
Head lights	Noise	Smoke & fumes	Right front 7 mm
Tail lights	Clutch	Performance	Left rear 7 mm
Indicators	CV joints	Noise	Right rear 6 mm
Dashboard warning light	ts Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake		Heater fan •
Window winder RR	• Indite blake	Suspension	
Rear view mirrors	Keys & Locking	Suspension performance	Seatbelts
Radio (basic test only)	Central locking	Steering performance	Horn
CD (basic test only)	Remote locking	• Shock absorbers	Turners Certified Key ✓ = Pass X = Fail • = Not applicable for this vehicle
Reversing camera	Number of keys	2	

Inspected by: John Lindsay