

## Turners Certified Imports 50 Point Check

Report ID: 18,595,661

Version: 1

Signature: .....

Created: 12 Oct 2018

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

IMPORTED VEHICLES	accredite	d inspection agency	and been te	st driven up to	o 50km/h fr	om cold.	Inpliance check	by all N	2171
Make:	Body Style:			Seats:	Good				
Model:	Odometer: 119,751 Kms			Good					
Year: VIN: 7AT0GF0BX18026691				Carpets:					
Under Carriage & Unde	er Bonnet I	Inspection Commen	<u>its</u>	Panels:	Good				
				Dashboard:	Good				
				Engine Timi	ng Mechanis	m:	Timing Chain		
General Comments				Evidence of	Cam Belt Rep	olacement:	Not Applicable	<u> </u>	
				Replaced At	(odometer r	eading):			
				Road Condi	tions During	Test Drive:	Wet		
Electrical		Transmission & Dri	ve	Engine			<b>Tyres</b> (lowest obs depth)	erved tread	
Battery		Operation		Oil level			Left front	3.5	mm
Head lights		Noise		Smoke & fur	mes		Right front	3.5	mm
Tail lights		Clutch	•	Performance	e		Left rear	3.5	mm
Indicators		CV joints		Noise			Right rear	3.5	mm
Dashboard warning light	s	Wheel bearings		Cooling Sys	stem		Spare	Yes	
Wipers (front & rear)		Wheel balance		Coolant con	ndition		Tools		
Window winder FL		Brakes		Performance	e		Interior		
Window winder FR		Performance		Radiator / H	oses (visual)		AC Operation		/
Window winder RL		Hand Brake					Heater fan		
Window winder RR			Ľ	Suspension	1		Seatbelts	[	
Rear view mirrors		Keys & Locking		Suspension	performance		Horn	[	
Radio (basic test only)		Central locking		Steering per	rformance				
CD (basic test only)		Remote locking		Shock absor	rbers		Turners Certified  ✓ = Pass  • = Not applica	<b>X</b> = Fail	
Reversing camera		Number of keys	2	Inspected by:	Xinghui Lii	n	Date:	11 Oct 2018	

Name: .....