

Turners Certified Imports 50 Point Check

 Report ID:
 18,608,979

 Version:
 4

 Created:
 28 Feb 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Subaru	Body Style:	Wagon
Model:	Exiga	Odometer:	124,810 Kms
Year:	2008	VIN:	7AT0GF1RX18004506

<u>Under Carriage & Under Bonnet Inspection Comments</u> Tidy.

General Comments

Good 7 seater AWD wagon . New Cam belt just fitted

Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	
Engine Timing Mechanism:		Cambelt
Evidence of Cam Belt Replacement:		Yes
Penlaced At (adameter reading):		124,840

Replaced At (odometer reading):124Road Conditions During Test Drive:Dry

Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation 🖌	Oil level	Left front 7.0 mm
Head lights	Noise	Smoke & fumes	Right front 7.0 mm
Tail lights	Clutch	Performance	Left rear 7.0 mm
Indicators	CV joints	Noise	Right rear 7.0 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake		Heater fan
Window winder RR		Suspension	Seatbelts
Rear view mirrors	Keys & Locking	Suspension performance	Horn
Radio (basic test only)	Central locking	Steering performance	
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key✓= PassX= Fail●= Not applicable for this vehicle
Reversing camera •	Number of keys 2	Inspected by: Daryll Timms	Date: 09 Jan 2019

Signature: