

## Turners Certified Imports 50 Point Check

Report ID: 18,623,960

Version:

Horn

**Turners Certified Key** 

**X** = Fail = Not applicable for this vehicle

Date: 03 Nov 2018

Signature: .....

✓ = Pass

Steering performance

Inspected by: Ca Thach

**Shock absorbers** 

2

10 Dec 2018 Created:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA

IMPORTED VEHICLES	edited inspection agency and beer	n test driven up to 50km/h from cold.	
Make: Mazda Body Style: SUV  Model: MPV Odometer: 110,394 Kms  Year: 2006 VIN: 7ATOC11EX18111796  Under Carriage & Under Bonnet Inspection Comments  General Comments		Seats: Good  Carpets: Good  Panels: Good  Dashboard: Good  Engine Timing Mechanism:  Evidence of Cam Belt Replacement:	Timing Chain Not Applicable
		Replaced At (odometer reading):  Road Conditions During Test Drive:	Wet
Electrical	Transmission & Drive	Engine	<b>Tyres</b> (lowest observed tread depth)
Battery	Operation	Oil level	Left front 7.0 mm
Head lights	Noise	Smoke & fumes	Right front 7.0 mm
Tail lights	Clutch	Performance	Left rear 7.0 mm
Indicators	CV joints	Noise	Right rear 7.0 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare N/A
Wipers (front & rear)	Wheel balance		Tools
Window winder FL	Brakes	Coolant condition	Interior
Window winder FR		Performance	
Window winder RL	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RR	Hand Brake	Suspension	Heater fan
Rear view mirrors	Keys & Locking	Suspension performance	Seatbelts

**Central locking** 

Remote locking

Number of keys

Radio (basic test only)

CD (basic test only)

Reversing camera