

## **Turners Certified Imports 50 Point Check**

Report ID: 18,627,095

Version:

Created: 05 Dec 2018

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

IMPORTED VEHICLES		accredited inspection agency and been test driven up to 30km/m nomicold.			
Make:	Subaru	Body Style	: Hatchback	Seats:	Good
Model:	Impreza	Odometer	<sub>:</sub> 68,568 Kms		Cood
Year:	2007	VIN:	7AT0GF09X18008407	Carpets:	Good
Under Carriage & Under Report Inspection Comments				Panels:	Good

Tidy .

General Comments
Nice 2WD hatch .

Dashboard: Good

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Replaced At (odometer reading):

Road Conditions During Test Drive: Dry

Electrical		
Battery		
Head lights		
Tail lights		
Indicators		
Dashboard warning lights		
Wipers (front & rear)		
Window winder FL		
Window winder FR		
Window winder RL		
Window winder RR		
Rear view mirrors		
Radio (basic test only)	<b>/</b>	
CD (basic test only)	<b>/</b>	
Reversing camera	•	





