

## **Turners Certified Imports 50 Point Check**

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

		Seats:GoodCarpets:GoodPanels:GoodDashboard:GoodEngine Timing Mechanism:Evidence of Cam Belt ReplacementReplaced At (odometer reading):Road Conditions During Test Drives	Data
Electrical	Transmission & Drive	Engine	<b>Tyres</b> (lowest observed tread depth)
Battery	Operation	Oil level	Left front 7 mm
Head lights	Noise	Smoke & fumes	Right front <b>7</b> mm
Tail lights	Clutch	Performance	Left rear 6 mm
Indicators	CV joints	Noise	Right rear 6 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance		Tools
Window winder FL	Brakes	Coolant condition	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake		Heater fan
Window winder RR	·	Suspension	Seatbelts
Rear view mirrors	Keys & Locking	Suspension performance	Horn
Radio (basic test only)	Central locking	Steering performance	
CD (basic test only)	Remote locking	Shock absorbers	<ul> <li>Turners Certified Key</li> <li>✓ = Pass X = Fail</li> <li>■ Not applicable for this vehicle</li> </ul>
Reversing camera •	Number of keys 1	Inspected by: Brad Lucas	Date: 16 Nov 2018