

Turners Certified Imports 50 Point Check

Report ID: 18,632,507

Version: 1

Created: 21 Nov 2018

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

IMPORTED VEHICLES	credited inspection agency and b	peen test driven up to 50km/h from cold.	impliance check by an NZTA
Make: Mitsubishi Model: Pajero Year: 2008 Under Carriage & Under B General Comments	Body Style: SUV Odometer: 112,134 Kms VIN: 7AT0CJ08X1810056 Connet Inspection Comments	Seats: Good Carpets: Good Panels: Good Dashboard: Good Engine Timing Mechanism: Evidence of Cam Belt Replacement: Replaced At (odometer reading): Road Conditions During Test Drive:	Cambelt No Dry
Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear)	Operation Noise Clutch CV joints Wheel bearings Wheel balance	Oil level Smoke & fumes Performance Noise Cooling System Coolant condition	Left front 7.0 mm Right front 7.0 mm Left rear 7.0 mm Right rear 7.0 mm Spare Yes Tools
Window winder FL Window winder FR	Brakes Performance	Performance Radiator / Hoses (visual)	Interior AC Operation
Window winder RL Window winder RR	Hand Brake	Suspension	Heater fan Seathelts

Reversing camera

Number of keys

Inspected by: Mathew Varghese

Date: 13 Nov 2018

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Keys & Locking

Central locking

Remote locking

Suspension performance

Steering performance

Shock absorbers

• Not applicable for this vehicle

X = Fail

Horn

Turners Certified Key

✓ = Pass