

Turners Certified Imports 50 Point Check

Report ID: 18,637,189

Version:

27 Nov 2018 Created:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Mazda Make: **Body Style: Hatchback** Verisa Odometer: 57,169 Kms Model: 7AT0C103X18319725 2008 VIN: Year:

Under Carriage & Under Bonnet Inspection Comments

General Comments


Good Seats: Good Carpets: Good Panels: Dashboard: Good


Timing Chain **Engine Timing Mechanism:** Not Applicable **Evidence of Cam Belt Replacement:**

Replaced At (odometer reading):


Wet **Road Conditions During Test Drive:**

Electrical Battery Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Reversing camera •





Inspected by: Xinghui Lin



Date: 21 Nov 2018