

Turners Certified Imports 50 Point Check

Report ID: 18,638,942

Version: 2

Created: 20 Nov 2018

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Toyota	Body Style:	Hatchback
Model:	Vitz	Odometer:	33,986 Kms
Year:	2009	VIN:	7AT0H63EX18080611

Under Carriage & Under Bonnet Inspection Comments

General Comments

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

Engine Timing Mechanism:

Evidence of Cam Belt Replacement:


Replaced At (odometer reading):


Timing Chain

Not Applicable

Wet


Electrical	
Battery	
Head lights	
Tail lights	
Indicators	
Dashboard warning lights	
Wipers (front & rear)	
Window winder FL	
Window winder FR	
Window winder RL	
Window winder RR	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	
Reversing camera	•





Inspected by: Xinghui Lin

Road Conditions During Test Drive:



Date: 20 Nov 2018