

Turners Certified Imports 50 Point Check

Report ID: 18,831,015

Version:


Created: 29 Nov 2018


Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA

IMPORTED VEHICLES	accredite	d inspection agency and bee	en test driven up	to 50km/h from	cold.	ŕ
Make: Subaru Model: Impreza	-	Style: Hatchback	Seats:	Good		
Model: Impreza Year: 2009	VIN:	7AT0GF09X18008512	Carpets:	Good		
Under Carriage & Under	Bonnet	nspection Comments	Panels:	Good		
			Dashboar	rd: Good		
			Engine Ti	ming Mechanism:	Cambelt	
General Comments			Evidence	of Cam Belt Replace	ement: No	
			Replaced	At (odometer readi	_	
			Road Con	nditions During Test	Drive: Dry	
Electrical		Transmission & Drive	Engine		Tyres (lowest of depth)	bserved tread
Battery		Operation	Oil level	U	Left front	7.0 mm
Head lights		Noise	Smoke &	fumes	Right front	7.0 mm
Tail lights		Clutch	Performal	nce	Left rear	7.0 mm
Indicators		CV joints	Noise		Right rear	7.0 mm
		Wheel bearings			Spare	Yes
Dashboard warning lights		Wheel bearings	Cooling S	System		4
Wipers (front & rear)		Wheel balance	Cooling S		Tools	

Head lights	
Tail lights	
Indicators	
Dashboard warning lights	
Wipers (front & rear)	
Window winder FL	
Window winder FR	
Window winder RL	
Window winder RR	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	
Reversing camera	•





Date: 22 Nov 2018