

Turners Certified Imports 50 Point Check

Report ID: 18,832,579

Version:

Created: 29 Nov 2018

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA

IMPORTED VEHICLES	accredited	Inspection agency and be	en test ariven up to	SUKM/N from Co	Ia.		
Make: Subaru Body Style: Hatchback Model: Impreza Odometer: 88,720 Kms Year: 2009 VIN: 7AT0GF09X18030085 Under Carriage & Under Bonnet Inspection Comments General Comments			Panels: Dashboard: Engine Timii	Good Good Good ng Mechanism: Cam Belt Replacem	Cambelt nent: No		
			Road Condit	(odometer reading	\\/_+	erved tread	
Electrical		Transmission & Drive	Engine		depth)	erved tread	
Battery		Operation	Oil level		Left front	4.5	mm
Head lights		Noise	Smoke & fur	mes	Right front	4.5	mm
Tail lights		Clutch	Performance	e	Left rear	4.5	mm
Indicators		CV joints	Noise		Right rear	4.5	mm
Dashboard warning ligh	ts 🚺	Wheel bearings	Cooling Sys	stem	Spare	Yes	
Wipers (front & rear)		Wheel balance			Tools		
Window winder FL		Brakes Brakes	Coolant con Performance		Interior		
Window winder FR			renormance				
Window winder RL		Performance	Radiator / Ho	oses (visual)	AC Operation		
Window winder PP		Hand Brake	Suspension		Heater fan		

•

Keys & Locking

Central locking

Remote locking

Number of keys

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Reversing camera

1

Suspension performance

Steering performance

Inspected by: Xinghui Lin

Shock absorbers

Date: 28 Nov 2018

X = Fail = Not applicable for this vehicle

Seatbelts

Turners Certified Key

✓ = Pass

Horn