

Turners Certified Imports 50 Point Check

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Subaru	Body Style:	Wagon
Model:	Exiga	Odometer:	97,692 Kms
Year:	2009	VIN:	7AT0GF1RX18007753

Under Carriage & Under Bonnet Inspection Comments

Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	
Engine Timii	ng Mechanism:	Cambelt
Evidonco of	Cam Bolt Poplacomont	No

General Comments

Evidence of Cam Belt Replacement: Replaced At (odometer reading):

Dry Road Conditions During Test Drive:

Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 7.0 mm
Head lights	Noise	Smoke & fumes	Right front 7.0 mm
Tail lights	Clutch	Performance	Left rear 7.0 mm
Indicators	CV joints	Noise	Right rear 7.0 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	
Window winder RL		Radiator / Hoses (Visual)	AC Operation
Window winder RR	Hand Brake	Suspension	Heater fan
Rear view mirrors	Keys & Locking	Suspension performance	Seatbelts
Radio (basic test only)	Central locking	Steering performance	Horn
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key✓= PassX= Fail●= Not applicable for this vehicle
Reversing camera •	Number of keys 1	Inspected by: Bobby Zhong	Date: 04 Dec 2018

Signature: