

## Turners Certified Imports 50 Point Check

Report ID: 18,836,475

Version:

Created: 30 Nov 2018

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA

IMPORTED VEHICLES	redited inspection agency and be	een test driven up to 50km/n from cold.	
Make: Mazda Body Style: Sedan  Model: Atenza Odometer: 94,712 Kms  Year: 2013 VIN: 7AT0C139X18102902  Under Carriage & Under Bonnet Inspection Comments		Seats: Good  Carpets: Good  Panels: Good  Dashboard: Good	
		Engine Timing Mechanism:	Timing Chain
General Comments		Evidence of Cam Belt Replacement	Not Applicable
		Replaced At (odometer reading):  Road Conditions During Test Drive	<sub>:</sub> Dry
Electrical	Transmission & Drive	Engine	<b>Tyres</b> (lowest observed tread depth)
Battery	Operation	Oil level	Left front 5.8
Head lights	Noise	Smoke & fumes	Right front 5.8 m
Tail lights	Clutch	• Performance	Left rear 5.4
Indicators	CV joints	Noise	Right rear 5.5 m
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake		Heater fan
Window winder RR		Suspension	Seatbelts
Rear view mirrors	Keys & Locking	Suspension performance	Horn
1			The state of the

Steering performance

Inspected by: Ian Dunn

**Shock absorbers** 

1

**Turners Certified Key** 

**X** = Fail = Not applicable for this vehicle

Date: 30 Nov 2018

Signature: .....

✓ = Pass

•

Central locking

Remote locking

Number of keys

Radio (basic test only)

CD (basic test only)

Reversing camera