

Turners Certified Imports 50 Point Check

Report ID: 18,839,018

Version:

Created: 02 Dec 2018

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

IMPORTED VEHICLES	redited inspection agency and been to	est driven up to 50km/h from cold.	Impliance check by an N21A
Make: Toyota	Body Style: Wagon	Seats: Good	
Model: Corolla Year: 2007	Odometer: 113,177 Kms VIN: 7AT0H64LX18016833	Carpets: Good	
Under Carriage & Under Bonnet Inspection Comments		Panels: Good	
		Dashboard: Good	
		Engine Timing Mechanism:	Timing Chain
General Comments		Evidence of Cam Belt Replacement:	Not Applicable
		Replaced At (odometer reading):	
		Road Conditions During Test Drive:	Wet
Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 3 mm
Head lights	Noise	Smoke & fumes	Right front 3 mm
Tail lights	Clutch	Performance	Left rear 3.5 mm
Indicators	CV joints	Noise	Right rear 3.5 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL		nadiator / noses (visual)	
Window winder RR	Hand Brake	Suspension	Heater fan
Rear view mirrors	Keys & Locking	Suspension performance	Seatbelts
Radio (basic test only)	Central locking	Steering performance	Horn

Remote locking

Number of keys

CD (basic test only)

Reversing camera

2

Shock absorbers

Inspected by: Xinghui Lin

Date: 02 Dec 2018

Pass X = FailNot applicable for this vehicle

Turners Certified Key