

## **Turners Certified Imports 50 Point Check**

Report ID: 18,839,808

Version:

05 Dec 2018 Created:

## **Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Suzuki Make: **Body Style: Hatchback** Swift Odometer: 94,408 Kms Model: 7AT0GK0CX18424370 2008 VIN: Year:

**Under Carriage & Under Bonnet Inspection Comments** Tidy.

**General Comments** 

Tidy little Swift.

**Electrical** 

**Battery** 

**Head lights** 

Tail lights

Indicators

Good Seats: Good Carpets: Good Panels: Dashboard: Good

Timing Chain **Engine Timing Mechanism:** Not Applicable **Evidence of Cam Belt Replacement:** 

Wet **Road Conditions During Test Drive:** 

Replaced At (odometer reading):

**Transmission & Drive** 

Operation Noise

Wheel bearings

Window winder FL

Window winder FR

Dashboard warning lights

Wipers (front & rear)

Window winder RL

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Reversing camera

Clutch

**CV** joints

Wheel balance

**Brakes** 

Performance

**Hand Brake** 

**Keys & Locking** 

Remote locking

Central locking

Number of keys

1

**Engine** 

Oil level

Smoke & fumes

Performance

Noise

**Cooling System** 

Coolant condition

Performance

Radiator / Hoses (visual)

**Suspension** 

Suspension performance

Steering performance

Shock absorbers

Tyres (lowest observed tread depth)

mm 2 Left front 2 mm Right front

1.6 Left rear 2 mm Right rear

Yes Spare

**Tools** 

**Interior AC Operation** 

Heater fan Seatbelts

**Turners Certified Key X** = Fail ✓ = Pass

= Not applicable for this vehicle

Inspected by: Daryll Timms Date: 05 Dec 2018

Horn

•