

## **Turners Certified Imports 50 Point Check**

Report ID: 18,839,820

Version:

Created: 03 Dec 2018

## **Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Mazda Make: **Body Style: SUV** 

Odometer: 69,767 Kms Premacy Model:

7AT0C133X18300242 2007 VIN: Year:

**Under Carriage & Under Bonnet Inspection Comments** 

Tidy.

**General Comments** 

Good 7 seater people mover.

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

Timing Chain **Engine Timing Mechanism:** 


Not Applicable **Evidence of Cam Belt Replacement:** 


Replaced At (odometer reading):

**Road Conditions During Test Drive:** 

Dry

Electrical	
Battery	<b>/</b>
Head lights	
Tail lights	
Indicators	
Dashboard warning lights	
Wipers (front & rear)	
Window winder FL	
Window winder FR	
Window winder RL	
Window winder RR	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	
Reversing camera	•







Inspected by: Daryll Timms Date: 03 Dec 2018	
--	--