

Turners Certified Imports 50 Point Check

Report ID: 18,840,016

Version:

03 Dec 2018 Created:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA


IMPORTED VEHICLES	edited inspection agency and been te	est ariven up to 50km/n from cola.	
	Body Style: Hatchback Odometer: 93,449 Kms VIN: 7AT0GKG7X18101259 Innet Inspection Comments	Seats: Good Carpets: Good Panels: Good Dashboard: Good	
		Engine Timing Mechanism:	Timing Chain
General Comments		Evidence of Cam Belt Replacement:	Not Applicable
		Replaced At (odometer reading): Road Conditions During Test Drive:	Dry
Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 8.0 mm
Head lights	Noise	Smoke & fumes	Right front 8.0 mm
Tail lights	Clutch	Performance	Left rear 8.0 mm
Indicators	CV joints	Noise	Right rear 8.0 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation


Radio (basic test only)	
CD (basic test only)	
Reversing camera	•

Window winder RL

Window winder RR

Rear view mirrors





Inspected by: Brad Lucas

Date: 01 Dec 2018