

## **Turners Certified Imports 50 Point Check**

 Report ID:
 18,840,037

 Version:
 3

 Created:
 14 Dec 2018

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Replaced At (odometer reading):

Make:	Subaru	Body Style:	Wagon
Model:	Exiga	Odometer:	129,425 Kms
Year:	2008	VIN:	7AT0GF1RX18002724

Under Carriage & Under Bonnet Inspection Comments

	Seats:	Average	
	Carpets:	Average	
]	Panels:	Average	
	Dashboard:	Average	
	Engine Timing Mechanism:		Cambelt
	Evidence of Cam Belt Replacement:		Yes

113,410

## **General Comments**

		Road Conditions During Test Drive	: Dry
Electrical	Transmission & Drive	Engine	<b>Tyres</b> (lowest observed tread depth)
Battery	Operation	Oil level	Left front 6.0 mm
Head lights	Noise	Smoke & fumes	Right front 6.0 mm
Tail lights	Clutch	Performance	Left rear 6.0 mm
Indicators	CV joints	Noise	Right rear 6.0 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake		
Window winder RR		Suspension	Heater fan
Rear view mirrors	Keys & Locking	Suspension performance	
Radio (basic test only)	Central locking	Steering performance	Horn
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key✓=PassX=Fail●=Not applicable for this vehicle
Reversing camera	Number of keys 1	Inspected by: Greg Morgan	Date: 06 Dec 2018

Signature: .....