

Turners Certified Imports 50 Point Check

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Seats:

Good

Make:	Mazda	Body Style:	Sedan
Model:	Atenza	Odometer:	98,560 Kms
Year:	2009	VIN:	7AT0C139X18102270

<u>Under Carriage & Under Bonnet Inspection Comments</u> Tidy.

General Comments

Good tidy car .

	Carpets: Panels: Dashboard:	Good Good Good		
	Engine Timing Mechanism: Evidence of Cam Belt Replacement:		Timing Chain Not Applicable	

Dry

Replaced At (odometer reading):

Road Conditions During Test Drive:

Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 6 mm
Head lights	Noise	Smoke & fumes	Right front 6 mm
Tail lights	Clutch	Performance	Left rear 6 mm
Indicators	CV joints	Noise	Right rear 6 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance		Tools
Window winder FL		Coolant condition	
Window winder FR	Brakes	Performance	Interior
	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake		Heater fan
Window winder RR		Suspension	Seatbelts
Rear view mirrors	Keys & Locking	Suspension performance	Seatbells
Radio (basic test only)	Central locking	Steering performance	Horn
CD (basic test only)	Remote locking	Shock absorbers	 Turners Certified Key ✓ = Pass X = Fail ■ Not applicable for this vehicle
Reversing camera •	Number of keys 1	Inspected by: Daryll Timms	Date: 03 Dec 2018

Signature: