

Turners Certified Imports 50 Point Check

Report ID: 18,841,126

Version: 1

Created: 03 Dec 2018

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Honda Body Style: SUV

Model: Stream Odometer: 82,944 Kms

Year: 2010 VIN: 7AT08GADX18112934

<u>Under Carriage & Under Bonnet Inspection Comments</u>

Tidy.

General Comments

Good 7 seater wagon.

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good


Engine Timing Mechanism: Timing Chain


Evidence of Cam Belt Replacement: Not Applicable

Replaced At (odometer reading):


Road Conditions During Test Drive: Wet

Electrical		
Battery	V	
Head lights		
Tail lights		
Indicators		
Dashboard warning lights		
Wipers (front & rear)		
Window winder FL		
Window winder FR		
Window winder RL		
Window winder RR		
Rear view mirrors		
Radio (basic test only)		
CD (basic test only)		
Reversing camera	•	





Inspected by: Daryll Timms



Tyres (lowest observed tread

Date: 03 Dec 2018