

2009

Year:

## **Turners Certified Imports 50 Point Check**

Report ID: 18,844,294

Version: 2

Created: 10 Dec 2018

## **Note: This report is not a warranty**

7AT0GF09X18002970

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Subaru Body Style: Hatchback

Model: Impreza Odometer: 80,767 Kms

VIN:

**Under Carriage & Under Bonnet Inspection Comments** 

General Comments

Seats: Average

Carpets: Average

Panels: Average

Dashboard: Average

Engine Timing Mechanism:


Evidence of Cam Belt Replacement:


Replaced At (odometer reading):


Road Conditions During Test Drive:

Dry

Electrical	
Battery	
Head lights	
Tail lights	
Indicators	
Dashboard warning lights	
Wipers (front & rear)	
Window winder FL	
Window winder FR	
Window winder RL	
Window winder RR	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	
Reversing camera	







**Tyres** (lowest observed tread

Inspected by:	Greg Morgan	Date:	05 Dec 2018	