

Turners Certified Imports 50 Point Check

Report ID: 18,851,921

Version:

13 Dec 2018 Created:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Mazda **Body Style: SUV** Make:

Odometer: 102,393 Kms Premacy Model:

7AT0C133X18100519 2011 VIN: Year:

Under Carriage & Under Bonnet Inspection Comments

Left front tyre side wall damage

General Comments

Electrical

Average Seats:

Average Carpets:

Average Panels:

Dashboard: Average

Timing Chain **Engine Timing Mechanism:**

Not Applicable **Evidence of Cam Belt Replacement:**


Replaced At (odometer reading):


Road Conditions During Test Drive:


Dry

Liectrical	
Battery	
Head lights	
Tail lights	
Indicators	
Dashboard warning lights	
Wipers (front & rear)	
Window winder FL	
Window winder FR	
Window winder RL	
Window winder RR	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	

Reversing camera







Tyres (lowest observed tread

Date: 13 Dec 2018