

Turners Certified Imports 50 Point Check

Report ID: 18,856,760

Version: 1

Created: 08 Jan 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

CERTIFIED IMPORTED VEHICLES	liagnostic testing undertaken. The ver- ccredited inspection agency and been t	nicle has undergone a thorough co est driven up to 50km/h from cold.	ompliance check by an NZTA
Make: Toyota Body Style: Van Model: Hiace Odometer: 66,106 Kms Year: 2015 VIN: 7AT0H60FX18176988 Under Carriage & Under Bonnet Inspection Comments General Comments		Seats: Good Carpets: Good Panels: Good Dashboard: Good Engine Timing Mechanism: Evidence of Cam Belt Replacement:	Cambelt No
		Replaced At (odometer reading): Road Conditions During Test Drive:	Dry
Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 7 mm
Head lights	Noise	Smoke & fumes	Right front 7 mm
Tail lights	Clutch	Performance	Left rear 7 mm
Indicators	CV joints	Noise	Right rear 7 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL Window winder RR	Hand Brake	Suspension	Heater fan 🗾
Rear view mirrors	Keys & Locking	Suspension performance	Seatbelts
Radio (basic test only)	Central locking	Steering performance	Horn
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key ✓ = Pass X = Fail • = Not applicable for this vehicle

Reversing camera

Inspected by: John Lindsay

3

Number of keys

Date: 08 Jan 2019